

DSA File #	X
DSA Appl. #	X
OSHPD#	
Permit #	165671

SAMPLING REPORT Project Name: 240 Highland Avenue Date: 5/14/2021 Project Address: 240 Highland Avenue, San Rafael CA SESF Job # 72639-1 Inspection Location: Retaining Wall Inspection(s) Performed: Concrete - Sampling Document(s) Reviewed: General Notes, 1/S2, 7/S4. Bottom half of wall. Sample Type: 4 x 8 Concrete Cylinders # Samples Taken: 1 Sample Size: Five 4x8s 16367AP cu. yds Placed: 24 Performed Placement Inspection PSI @ days. 28 Design - Slump: 6 in. Design - Flow: in. Design - Air: Mix Design #: Shamrock Mix 6367AP Design - Strength: 3000 Sample Description/Location: First lift in wall at Line 1/A-C on 1/S2 per 7/S4. Time: 8:55 am Mix Time: 50 min. Load #: 2 Weather Concrete Temp: 64 ° Air Temp: 52 ° Yucky Slump: 6 in. Flow: in. Air: % Unit Weight: PCF Performed water control, including addition of water, slump test, verified trip tickets and mix design Performed batch plant inspection Material Cement Materials Aggregates - Ibs Water - gals or lbs Admixtures Quantities (+/-3%)Amount (+/-1% or +/- 3% of Scale) (+/-2% ind., +/-1% cum., +/- 0.3% Scale) (+/-1%)(cys) Load # Truck # Cement Pozzolan CA 1 CA 2 FA₁ Total FA 2 No 1 No 2 Batched Agg Tested Set Sample Length Dia. Area Load Break Age Width **PSI** By (lbs.) Avg. (in.) | Avg (in.) | (Avg.(in.) (in.) Type 1 of 1 LAB USE Work WAS WAS NOT Inspected in Accordance with the Requirements of DSA OSHPD V JURISDICTION Approved Documents N/A Work Inspected MET DID NOT MEET The Requirements of the DSA OSHPD JURISDICTION Approved Documents N/A Material WAS WAS NOT Sampled and Tested in Accordance with the Requirements of DSA OSHPD JURISDICTION Approved Documents N/A Material Tested MET DID NOT MEET The Requirements of the DSA OSHPD JURISDICTION Approved Documents N/A Work Not In Compliance: Notified (Required) Cylinders are along the fence outside the job Name: Doug Smith Attachments: _____ Bun

Signature:

Certification # 8356911

Emp. ID: 9076 Page <u>1</u> of <u>1</u>