



SMITH-EMERY SAN FRANCISCO  
 1940 Oakdale Ave, San Francisco, CA 94124  
 (415) 642-7326  
 LEA #56

DSA File # N/A  
 DSA Appl. # N/A  
 OSHPD # N/A  
 Permit # 165671

**DAILY SPECIAL INSPECTION REPORT**

Project Name: 240 Highland Avenue San Rafael Date: 6/21/2021  
 Project Address: 240 Highland Avenue San Rafael SESF Job # 72639-1  
 Inspection Location: Retaining wall at C/1 IR # —  
 Inspection(s) Performed: Epoxy Installation  
 Document(s) Reviewed: Project plans / details / Approve documents

**Inspection Report:**

EPOXY;

Product: Simpson set- XP EXP. 12/30/22


Inspected holes clean-out and epoxy installation for #5 dowels at Retaining wall at C/1. Minimum embed observed throughout, min req'd embed 6 1/4 in. Holes were cleaned with air prior to installation of epoxy dowels. Dowels/epoxy were installed in accordance with manufacture's recommendations and approve plans concrete note #9 & S2.

Work  WAS  WAS NOT Inspected in Accordance with the Requirements of  DSA  OSHPD  JURISDICTION Approved Documents  N/A  
 Work Inspected  MET  DID NOT MEET The Requirements of the  DSA  OSHPD  JURISDICTION Approved Documents  N/A  
 Material  WAS  WAS NOT Sampled and Tested in Accordance with the Requirements of  DSA  OSHPD  JURISDICTION Approved Documents  N/A  
 Material Tested  MET  DID NOT MEET The Requirements of the  DSA  OSHPD  JURISDICTION Approved Documents  N/A

**Work Not In Compliance:** \_\_\_\_\_ Notified (Required) \_\_\_\_\_

Attachments: \_\_\_\_\_

Name: Juan Barrera

Signature: 

Certification # ICC# 8714560

Emp. ID: 9091 Page 1 of 1